



Figure 2. Installation of the optical fibre sensors: (a) installation of clad DOFS cable in a reinforcement bar by inserting it into a previously milled groove; (b-c) installation of clad DOFS on the surface of a reinforcement bar by mechanically anchoring the cable to the reinforcement with electric tape; (d) installation of clad DOFS attached to the concrete surface inserted in previously milled grooves.